



১৯ অগ্রহায়ণ ১৪৩২

DU in Media

04 December 2025

ইনকিলাব

ভোরের ডাক



ঢাবি উপাচার্যের সঙ্গে জাপানের এমইউএফজি ব্যাংকের এমডির সৌজন্য সাক্ষাৎ

জাপানের এমইউএফজি ব্যাংক লিমিটেড (মিতসুবিশি ইউএফজে ফাইন্যান্সিয়াল গ্রুপ)-এর ব্যবস্থাপনা পরিচালক মি. কেনজি কিমুরা গতকাল ঢাকা বিশ্ববিদ্যালয়ের উপাচার্য অধ্যাপক ড. নিয়াজ আহমদ খানের সঙ্গে তার কার্যালয়ে সৌজন্য সাক্ষাৎ করেছেন।

-প্রেস বিজ্ঞপ্তি

আলোকিত বাংলাদেশ



ঢাবি উপাচার্যের সঙ্গে জাপানের এমইউএফজি ব্যাংকের এমডির সৌজন্য সাক্ষাৎ

আলোকিত ডেস্ক : জাপানের এমইউএফজি ব্যাংক লিমিটেড (মিতসুবিশি ইউএফজে ফাইন্যান্সিয়াল গ্রুপ)-এর ব্যবস্থাপনা পরিচালক মি. কেনজি কিমুরা গতকাল দুপুরে ঢাকা বিশ্ববিদ্যালয়ের উপাচার্য অধ্যাপক ড. নিয়াজ আহমদ খানের সঙ্গে তার কার্যালয়ে সৌজন্য সাক্ষাৎ করেছেন। এ সময় একই ব্যাংকের কর্মকর্তা মি. আহমাদ সাত্তিম রব তাঁর সঙ্গে ছিলেন। সাক্ষাৎ কালে তারা ঢাকা বিশ্ববিদ্যালয়ের অসচ্ছল শিক্ষার্থীদের আর্থিক সহায়তা প্রদানসহ বিভিন্ন বিষয়ে আলোচনা করেন। উপাচার্য অধ্যাপক ড. নিয়াজ আহমদ খান ঢাকা বিশ্ববিদ্যালয়ের শিক্ষার্থীদের জন্য বৃত্তির সংখ্যা বৃদ্ধির ক্ষেত্রে এমইউএফজি ব্যাংকের ব্যবস্থাপনা পরিচালকের সহযোগিতা কামনা করেন। সূত্র: সংবাদ বিজ্ঞপ্তি



The Country Today



Earthquake issue

Technical committee of BUET visits 4 more halls at DU

DU Correspondent

A sub-committee comprising experts from BUET visited 4 more halls of Dhaka University on Wednesday for the technical inspection and evaluation of various residential halls after the earthquake. The halls are - Bangladesh-Kuwait Friendship Hall, Salimullah Muslim Hall, Rokeya Hall and Sir P. J. Hartog International Hall.

During the visit, BUET Civil Engineering Department Professor Dr. Ishtiaq Ahmed, BUET Civil Engineering Department Professor Dr. Rakib Ahsan, the principal of the concerned hall, university engineers, DUCSU Common Room, Reading Room and Cafeteria Secretary Umme Salma, DUCSU Career Development Secretary Mazharul Islam and representatives of the Hall Parliament were present.

Inspection Report of Bangladesh Kuwait Friendship Hall: During the inspection of the 3 (three) storey "Shikdar Monowara" building

Continued to page 2

Technical committee

located inside the Bangladesh-Kuwait Friendship Hall, it was seen that the main structure (Beam-Column) of the building remained intact after the earthquake and no cracks were formed in it.

It is to be noted that after the construction of the building, a crack appeared in the cantilever part outside the building, and the risky part was later demolished. BUET expert members have inspected the building on site several times. In addition, the PWD (Design Circle-1) team inspected the building on site on December 19, 2023 to verify its suitability for living. After evaluating the structural design and information obtained from the building and inspecting the existing condition, the team members gave their opinion that the 3 (three)-storey building is suitable for safe living in its current condition. At that time, in view of the opinion of the PWD (Design Circle-1), various internal repairs including roof repairs were carried out in the building.